



Delta EV Charger Software Release Note

General Information

Compatible Model	AC MAX
Compatible Model Name	EIAW-E (EU)
Software Revision	v01.26.31.00
MCU FW Revision	01.00.35.00 (EU)
Software File Name	ACMAX_FW_v01.26.31.00.bin
Date of Release	2023/12/28

Improvement and bug fixed:

1. [DNIW-1769] [OCPP] add the GetConfigurationConf OCPP Log.
2. [DNIW-1622] [OCPP] OCPP will reject changeconfig MeterValueSampledData and MeterValuesAlignedData
3. [DNIW-1447] Factory reset should remove OCPP msg Queue file and ALL OCPP configuration.
4. [DNIW-1651] Transaction ID 348 keeps alive since the first OCPP log, remotestart all rejected.
5. [DNIW-1744] [OCPP]ACMAX need add support for OCPP configure MAX Current
6. [DNIW-1696] [Internal][optimize]ACMAX should not print WiFi scan log when SSID is not set.
7. [DNIW-1722] [OCPP] OCPP16J sometimes encounter deadlock
8. [DNIW-1700] [ACMAX] Web OCPP URL support 256 characters
9. [DNIW-1674] [Internal]ACMAX OCPP16J always timeout after reconnect to Internet
10. [DNIW-1658] the color of LED is red when do firmware upgrade
11. [DNIW-1641] [ACMAX] Optimize page caching issues
12. [DNIW-1590] [GUI]HTTPBasicAuthEnable not support special characters,but GUI has no limit of AuthorizationKey
13. [DNIW-1575] [ACMAX] Unable to use the HTTP protocol to log in to the page from the wireless STA port
14. [DNIW-1549] ubi volume should can be re-create when ubiattach fail.
15. [DNIW-1448] EVPT3215MWE offline RFID can not work
16. [DNIW-1490] NAND u-boot-env too few good blocks fail
17. [DNIW-1512] Adjust the 4G log output
18. [DNIW-1375] [GUI]The eye icon for displayed and hidden password is reversed
19. (feature): DNIW-1517 [ACMAX] WiFi Security Add "None" Connection Method