USB port checking

D006_v1.0

Remove filter cover with T20 torx driver
- Release the two screws on top.
- Release the two screws on bottom and pull out the latch.
- Open and remove the filter cover.

Remove protection cover

Check USB cable connection

➢ 1. Re-plug USB cable on CHAdeMO CSU (left)

➢ 2. If cable well connect but USB port at button still failed, go step 3

➢ 3. Un-plug USB cable on CHEdeMO CSU and plug USB directly to CHAdeMO CSU. If work, go to step 4, otherwise go to step 5.

➢ 4. Replace USB cable.

➢ 5. Replace CHAdeMO CSU.

Smarter. Greener. Together.

To learn more about Delta, please visit www.deltaww.com.